



SAFETY ALERT — FIRST ALERT SMOKE/CO ALARMS RECALL

From: Steve Cloutier	Reference Number: 05-02-06	Date: May 2, 2006
-------------------------	-------------------------------	----------------------

Effective Immediately

NEWS from CPSC

U.S. Consumer Product Safety Commission

Office of Information and Public Affairs
FOR IMMEDIATE RELEASE
May 2, 2006
Release #06-151

Washington, DC 20207
Firm's Hotline: (800) 323-9005
CPSC Recall Hotline: (800) 638-2772
CPSC Media Contact: (301) 504-7908

First Alert Smoke Alarms and Combination Smoke/CO Alarms Recalled for Rapidly Draining Battery Power

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately unless otherwise instructed.

Name of Product: First Alert® ONELINK™ Battery-Powered Smoke and Combination Smoke/Carbon Monoxide (CO) Alarms **Units:** About 145,890 (About 52,400 were sold to consumers)

Manufacturer: BRK Brands Inc., a subsidiary of First Alert Inc., of Aurora, Ill.

Hazard: These alarms can drain the power from batteries rapidly, causing premature low battery power. Consumers will be alerted to the low battery power and the need to replace the battery by a chirping of the unit. If the batteries on the smoke/CO alarm are not replaced before the battery power terminates, the alarm will not detect smoke in the event of a possible fire and the presence of carbon monoxide.

Incidents/Injuries: CPSC and First Alert Inc./BRK Brands Inc. have received about 329 reports of premature low battery power in these alarms. There have been no reports of injuries, incidents or alarms failing to detect smoke or carbon monoxide.

Description: The recall involves ONELINK™ battery-powered smoke and combination smoke/CO alarms. "First Alert" and "ONELINK™" are printed on the front of the alarm. The model number and date code are printed on the back of the alarm. Model number SA500 or SCO500 with a date code prior to March 3, 2006 are included in this recall.

Sold at: Department, home and hardware stores nationwide from June 2005 through March 2006 for between \$45 and \$75. **Manufactured In:** Mexico

Remedy: Consumers should contact First Alert Inc./BRK Brands Inc. immediately to receive a replacement alarm. Until a new alarm is received, consumers should test the batteries in the alarm weekly by pressing the "test" button. If the alarm signals a low battery alert, consumers should immediately replace the batteries. Consumers should not remove their alarms until they have received a replacement alarm.

Consumer Contact: For more information, contact First Alert Inc./BRK Brands Inc. at (800) 323-9005 between 8:30 a.m. and 6 p.m. ET Monday through Friday or visit the firm's web site at www.firstalert.com

Safety Alert — First Alert Smoke/CO Alarms RECALL

Firm's Hotline: (800) 323-9005
CPSC Recall Hotline: (800) 638-2772
CPSC Media Contact: (301) 504-7908

